



PRESSURE/TORQUE CONVERSION CHART

17MD

PRESSURE (PSI)	FT. LBS.	NM
1000	1653	2241
1200	2012	2728
1400	2368	3211
1600	2772	3758
1800	3147	4267
2000	3471	4706
2200	3917	5310
2400	4286	5811
2600	4658	6315
2800	5028	6817
3000	5398	7319
3200	5770	7823
3400	6139	8324
3600	6512	8830
3800	6886	9336
4000	7257	9839
4200	7629	10344
4400	7977	10816
4600	8339	11307
4800	8698	11792
5000	9118	12362
5200	9416	12766
5400	9791	13274
5600	10161	13776
5800	10536	14285
6000	10912	14795
6200	11287	15303
6400	11677	15832
6600	12047	16333
6800	12435	16859
7000	12823	17385
7200	13200	17896
7400	13571	18400
7600	13919	18872
7800	14300	19388
8000	14717	19954
8200	15042	20395
8400	15433	20924
8600	15833	21466
8800	16191	21952
9000	16545	22432
9200	16935	22961
9400	17321	23484
9600	17696	23993
9800	18060	24487
10000	18446	25009