



PRESSURE/TORQUE CONVERSION CHART

32MD

PRESSURE (PSI)	FT. LBS.	NM
1000	2957	4009
1200	3747	5080
1400	4398	5963
1600	5125	6949
1800	5739	7781
2000	6476	8780
2200	7113	9644
2400	7704	10446
2600	8349	11320
2800	9048	12267
3000	9615	13036
3200	10260	13911
3400	10915	14799
3600	11578	15698
3800	12214	16560
4000	12901	17491
4200	13459	18248
4400	14137	19167
4600	14742	19987
4800	15424	20913
5000	16029	21732
5200	16658	22585
5400	17337	23505
5600	18005	24412
5800	18638	25269
6000	19359	26247
6200	19947	27044
6400	20635	27977
6600	21324	28911
6800	21927	29729
7000	22595	30635
7200	23291	31578
7400	23961	32487
7600	24589	33338
7800	25230	34208
8000	25890	35103
8200	26555	36004
8400	27217	36901
8600	27886	37808
8800	28581	38750
9000	29225	39623
9200	29878	40509
9400	30558	41431
9600	31195	42295
9800	31857	43192
10000	32523	44095