



PRESSURE/TORQUE CONVERSION CHART

.7MD

PRESSURE (PSI)	FT. LBS.	NM
1000	64	86
1200	79	108
1400	95	128
1600	110	149
1800	126	171
2000	140	190
2200	156	212
2400	172	233
2600	189	256
2800	205	277
3000	221	299
3200	237	321
3400	253	343
3600	270	366
3800	287	389
4000	302	410
4200	319	433
4400	335	454
4600	352	477
4800	368	498
5000	384	521
5200	401	543
5400	417	565
5600	434	588
5800	450	610
6000	466	632
6200	483	654
6400	499	676
6600	515	699
6800	531	720
7000	548	743
7200	564	765
7400	581	787
7600	598	811
7800	614	832
8000	631	856
8200	647	877
8400	664	900
8600	679	921
8800	695	943
9000	711	964
9200	728	987
9400	745	1010
9600	761	1031
9800	778	1054
10000	793	1076