



PRESSURE/TORQUE CONVERSION CHART

**.75IBT**

PRESSURE IN PSI	FT. LBS.	N-m
1500	115	156
1600	123	167
1800	139	189
2000	156	211
2200	171	232
2400	188	254
2600	203	275
2800	219	297
3000	235	318
3200	250	340
3400	266	361
3600	282	382
3800	298	404
4000	313	425
4200	329	446
4400	344	467
4600	360	488
4800	374	508
5000	389	528
5200	405	549
5400	419	568
5600	433	587
5800	448	607
6000	462	626
6200	476	645
6400	489	664
6600	503	682
6800	516	700
7000	530	719
7200	544	737
7400	558	756
7600	572	775
7800	586	794
8000	599	812
8200	613	831
8400	626	849
8600	640	868
8800	653	886
9000	667	905
9200	682	925
9400	695	942
9600	709	961
9800	723	980
10000	735	997

