



PRESSURE/TORQUE CONVERSION CHART

**14HP**

PRESSURE IN PSI	FT. LBS.	N-m
1500	1775	2407
1600	1899	2575
1800	2144	2907
2000	2390	3240
2200	2637	3575
2400	2883	3909
2600	3130	4244
2800	3376	4577
3000	3623	4912
3200	3873	5251
3400	4124	5591
3600	4374	5930
3800	4625	6271
4000	4876	6611
4200	5130	6955
4400	5383	7298
4600	5638	7644
4800	5892	7988
5000	6146	8333
5200	6405	8684
5400	6665	9036
5600	6925	9389
5800	7185	9741
6000	7445	10094
6200	7700	10440
6400	7955	10785
6600	8211	11132
6800	8466	11478
7000	8721	11824
7200	8977	12171
7400	9233	12518
7600	9488	12864
7800	9744	13211
8000	10000	13558
8200	10255	13904
8400	10509	14248
8600	10764	14594
8800	11018	14938
9000	11273	15284
9200	11517	15615
9400	11760	15944
9600	12003	16274
9800	12247	16604
10000	12500	16948

