



PRESSURE/TORQUE CONVERSION CHART

2HP

PRESSURE IN PSI	FT. LBS.	N-m
1500	220	298
1600	235	319
1800	267	362
2000	298	404
2200	330	447
2400	361	489
2600	393	533
2800	424	575
3000	456	618
3200	488	662
3400	520	705
3600	552	748
3800	585	793
4000	617	837
4200	648	879
4400	680	922
4600	711	964
4800	743	1007
5000	774	1049
5200	807	1094
5400	840	1139
5600	874	1185
5800	907	1230
6000	940	1274
6200	972	1318
6400	1004	1361
6600	1036	1405
6800	1068	1448
7000	1100	1491
7200	1133	1536
7400	1166	1581
7600	1199	1626
7800	1232	1670
8000	1265	1715
8200	1298	1760
8400	1330	1803
8600	1362	1847
8800	1395	1891
9000	1427	1935
9200	1459	1978
9400	1489	2019
9600	1521	2062
9800	1552	2104
10000	1590	2156

