



PRESSURE/TORQUE CONVERSION CHART

**14HP**

PRESSURE IN PSI	FT. LBS.	N-m
1000	1245	1689
1200	1537	2084
1400	1800	2440
1600	2061	2795
1800	2312	3136
2000	2611	3540
2200	2880	3905
2400	3150	4272
2600	3418	4634
2800	3685	4997
3000	3947	5353
3200	4218	5720
3400	4488	6085
3600	4760	6455
3800	5030	6821
4000	5286	7167
4200	5568	7550
4400	5803	7868
4600	6108	8282
4800	6348	8608
5000	6646	9012
5200	6897	9352
5400	7192	9752
5600	7460	10116
5800	7705	10448
6000	8008	10859
6200	8244	11179
6400	8513	11543
6600	8792	11922
6800	9062	12288
7000	9336	12659
7200	9611	13032
7400	9885	13405
7600	10172	13794
7800	10445	14164
8000	10700	14510
8200	10995	14910
8400	11272	15284
8600	11549	15660
8800	11801	16002
9000	12092	16397
9200	12352	16749
9400	12627	17122
9600	12892	17481
9800	13177	17868
10000	13443	18229

