



PRESSURE/TORQUE CONVERSION CHART

2HP

PRESSURE (PSI)	FT. LBS.	NM
1000	162	220
1200	180	244
1400	214	290
1600	265	359
1800	299	405
2000	335	454
2200	369	500
2400	401	544
2600	436	591
2800	471	639
3000	505	685
3200	539	731
3400	574	778
3600	610	827
3800	643	872
4000	678	919
4200	712	965
4400	747	1013
4600	782	1060
4800	817	1108
5000	852	1155
5200	886	1201
5400	920	1247
5600	955	1295
5800	991	1344
6000	1025	1390
6200	1058	1434
6400	1094	1483
6600	1130	1532
6800	1164	1578
7000	1197	1623
7200	1234	1673
7400	1268	1719
7600	1303	1767
7800	1337	1813
8000	1374	1863
8200	1406	1906
8400	1441	1954
8600	1475	2000
8800	1510	2047
9000	1546	2096
9200	1581	2144
9400	1615	2190
9600	1651	2238
9800	1685	2285
10000	1714	2324